




EJE SHAFT ARBRE WELLE




E2




E3




E4




E5



E38




E57




E58


CONEXIONES CONNECTIONS
CONNEXIONS ANSCHLUSSART




C2




C3



C4




C5




C35


ESQUEMA ELÉCTRICO WIRING DIAGRAM
SCHEMA ÉLECTRIQUE SCHALTBIKD



EE2




EE3




F3


CURVAS CURVES COURBES KURVEN




32




33



34



35



36